

Memo

To: Wal-Mart Supercenter North File
From: Bob Corson
Date: July 6, 2001
Subject: Inspection - Grease


cc: Randy Lyman, Wayne Latimer


In response to the sewer blockage behind the Waffle House, between manholes 1 and 4 map JA-K-L 18 I inspected the grease traps of the two businesses that are tributary to that line segment, ie, the McDonalds Restaurant, 2811 N. Kansas Expressway, and the Wal-Mart Supercenter, 2825 N. Kansas Expressway. My inspection of the sampling manhole at the McDonalds revealed little evidence of grease. I talked to the assistant manager "Mandy". She said that they had their grease trap cleaned every month but she couldn't remember who pumped it out. I then checked manhole 12 on map JA-K-L 18. There appeared to be some grease from the line that serves the Wal-Mart Supercenter but none from the line that serves the McDonalds. See attached map.

At the Wal-Mart I contacted the manager who was on duty, Brian Knight, about the grease problem. He indicated that Grants pumped out their grease trap. He thought that they pumped the grease trap every month but he would check and call me back. Later in the day Mr. Knight left me a voice message indicating that Grants was pumping the grease trap every three months but would increase their pump-out frequency to every other month.

I checked our hauled waste manifests and found the last pump-out by Grants at the Wal-Mart was on May 14, 2001.

2825 N. KANSAS EXPRESSWAY





DEAD END SEWER

EVERGREEN

JA-K-L 1B
W1

MH 4

MH 5

MH 1

KANSAS

EXPRESSWAY

3

5

33

34